

Thermal Analysis Concealment Lifecycle

Six Steps To A Worry-Free Design

DOCUMENTATION

Provide CD's, Lease Exhibits, RFDS & equipment specs to Raycap sales team.



STEP 01

STEP 02



FIT-UP

Raycap will complete equipment fit and identify pinch points.

INITIATE THERMAL ANALYSIS

Using information from steps 1 and 2.



STEP 03

STEP 04



THERMAL ANALYSIS RESULTS

If results pass, move to step 5.

if not...



...further evaluation of equipment positioning, location, concealment size, fans, etc. will be incorporated to achieve a passing result.


DESIGN

Move to design & engineering phase of project.



STEP 05

STEP 06



FABRICATE

Begin concealment fabrication.